






CL2Bm1 Board
(C) L&R ING. 2010

KINGSTON
SD 2GB

I/O

TTL
LEVEL



SPI



FIRMWARE UPDATE